Cambria Automotive Co. Inc.

Edison
116 Talmadge Road
Phone: (732) 985-6500

Elizabeth
565 Dowd Avenue
(908) 354-2100

Remit To
Cambria Companies
P.O. BOX 51061
Newark, NJ 07101-5161

Customer: CASH SALE TAXABLE
100 JAR TRUCKING
53 COTTAGE ST APT 2
LYNN, MA 01905

617 872-5622

Ship To: CASH SALE TAXABLE
LYNN, MA 01905

REPRINT CUSTOMER INVOICE
S84630
Invoice Date: 02-26-15

Tax ID: **Tax ID Date:** 03-11-99

Year	Make / Model	VIN	License	Mileage	Unit / Stock	Key Tag
2000	PETERBILT / 379	1XP5DB9X7YN522434	A84454	1325945	03	

Open Date / Time	Delivery Date	Delivery Mileage	CPL/ARRG	Service Writer	Authorization	P.O. Number
02-11-15 / 09:38AM	01-01-00			CC*BS		

Engine Model / Serial #	Transmission Model/Serial #	Rear Axel Model/Serial #	Rear Ratio
/	/		

Complete	Memo
02-26-15	

1 CUSTOMER REQUESTS TO HAVE HIS CATERPILLAR 3406E ENGINE OVERHAULED
CUSTOMER LEFT A $10,000. DEPOSIT FOR REPAIRS
CHECKED OUT UNIT, REMOVED THE TIMING COVER, DRAINED THE COOLANT, DRAINED THE OIL, REMOVED THE RADIATOR ASSEMBLY, FOUND THE FAN CLUTCH ADJUSTER BOLT SEIZED, REMOVED AND REPLACED FAN CLUTCH ADJUSTING BOLT, REMOVED THE TIMING GEAR, REMOVED THE CYLINDER HEAD, REMOVED THE TURBO, REMOVED THE EXHAUST MANIFOLD, REMOVED THE THERMOSTAT HOUSING, REMOVED THE WATER PUMP, REMOVED THE OIL PAN, REMOVED THE PICK UP TUBE, REMOVED THE OIL PUMP, REMOVED THE STIFFENER PLATE, REMOVED THE PISTON COOLING NOZZLE TO INSPECT AND FOUND THE NOZZLES WERE TOO OPEN AND NEED TO BE REPLACED, REMOVED THE PISTONS, REMOVED THE PISTON LINERS, INSPECTED THE CYLINDER BLOCK FOR DAMAGE AND IT IS IN GOOD CONDITION, CLEANED THE CYLINDER BLOCK, CLEANED THE CYLINDER BLOCK THREADS, INSPECTED THE ROCKER ARMS AND SHAFT DUE TO THE VALVE ON CYLINDER #1 BEING BROKEN, UPON INSPECTION FOUND THE CAMSHAFT NEEDS TO BE REPLACED, 3 ROCKER ARMS ON CYLINDER #1 TO BE REPLACED, AND FUEL INJECTOR ROCKER ARMS FOR CYLINDER #'S 2, 3, AND 6, REPLACED THE PISTONS, REPLACED THE ROAD BEARINGS, REPLACED THE PISTON COOLING NOZZLES, REPLACED THE OIL PUMP, INSTALLED NEW O-RINGS FOR PICKUP TUBES, REINSTALLED STIFFENER PLATE, CLEANED THE OIL PAN OF DIRT AND DEBRIS AND REINSTALLED WITH NEW GASKET, REPLACED HOOD CABLE, REPLACED THE FRONT CAMSHAFT SEAL, REPLACED THE FRONT MOTOR MOUNTS, INSTALLED THE DAMPERS, INSTALLED NEW CAMSHAFT ON CYLINDER HEAD, REPLACED THE GASKET ON CYLINDER HEAD, REPLACED THE SPACER PLATE FOR THE CYLINDER HEAD, INSTALLED NEW CYLINDER HEAD AND TIMING GEAR WITH NEW HARDWARE AND GASKETS, INSTALLED NEW ROCKER ARMS, INSTALLED 6 NEW INJECTORS WITH NEW HARDWARE AND NEW MOUNTING BOLTS, INSTALLED NEW INJECTOR HARNESS, INSTALLED VALVE BRIDGE AND ADJUST THE VALVE AND JAKE BRAKE, REINSTALLED THE VALVE COVER WITH NEW GASKET, REPLACED THE THERMOSTAT AND SEAL, REPLACED THE WATER PUMP, CLEANED THE EXHAUST MANIFOLD, REINSTALLED THE EXHAUST MANIFOLD WITH NEW GASKETS, SPACERS AND STUDS, INSTALLED NEW TURBO WITH NEW OUTLET CLAMP AND NEW HARDWARE, REPLACED THE MOUNTING BRACKET AND BOLT FOR THE A/C AND ALTERNATOR, REINSTALLED THE RADIATOR WITH NEW MOUNTING KIT AND HARDWARE, INSTALLED A/C PIPING AND CHARGED THE A/C SYSTEM, INSTALLED NEW FUEL FILTERS, INSTALLED NEW OIL FILTERS, INSTALLED NEW ENGINE OIL, INSTALLED NEW COOLANT, INSTALLED NEW RADIATOR CAP, REINSTALL ALL OTHER ACCESS COMPONENTS, PROGRAMMED THE FUEL INJECTORS, PROGRAMMED THE ECU, ROADTESTED UNIT AND IT IS WORKING PROPERLY,

CUSTOMER

Year	Make / Model	VIN	License	Mileage	Unit / Stock	Key Tag
2000	PETERBILT / 379	1XP5DB9X7YN522434	A84454	1325945	03	

Open Date / Time	Delivery Date	Delivery Mileage	CPL/ARRG	Service Writer	Authorization	P.O. Number
02-11-15 / 09:38AM	01-01-00			CC*BS		

Engine Model / Serial #	Transmission Model/Serial #	Rear Axel Model/Serial #	Rear Ratio
/	/		

Complete	Memo
02-26-15	

THANK YOU!

TOTAL LABOR	6,885.00
TOTAL PARTS	155.17
TOTAL GAS/OIL	176.45
TOTAL PETERBILT	711.42
TOTAL CAT	16,672.88
TOTAL OTHER	121.98

Qty	Part Number	Description	Unit	Extended
1	5166-27100	PX RED THREADLOCK 271 6M	4.53	4.53
1	5839-FF105	FUEL FILTER SPIN-ON	7.19	7.19
1	5166-51813	PX GASKET MAKER 518 50ML	13.16	13.16
2	3AX1855	SCREW MACH	15.85	31.70
2	25095352	NUT RETAINER	2.16	4.32
4	83AX872	CLAMP	17.28	69.12
1	25017798	HOSE	25.15	25.15
4	4710-05084	CRC BRAKLEEN BRAKE PARTS	3.30	13.20
2	4710-05025CA	CRC ENGINE DEGREASER 12X1	3.89	7.78
1	5166-59214	PX THREAD SEALANT 592 6M	3.55	3.55
12	SL-94042SGAL	ANTIFREEZE,ELC	12.66	151.92
1	AP2759	ADAPTER-PIPE STL ST 9/16M	2.30	2.30
1	AP3393	ADAPTER-SAE45 BRS MSTRCON	0.89	0.89
1	FG4039	FITTING-ELBOW 90DEG #10 H	9.86	9.86
1	FG3987	FITTING-SAE45 STL FSTRSWV	12.59	12.59
3	HE2209	HOSE-HYD/AIR #8X250' 100R	3.64	10.92
1	HE2222	HOSE-HYD/AIR #10X250' 100	4.14	4.14
2	FG3792	FITTING-SAE45 STL FSTRSWV	8.26	16.52
1	CM4324	CLAMP-CONST TORQUE 32	8.51	8.51
1	FG3168	FTG-A/C. #08 90 C0S W/P0R	4.60	4.60
1	FG3220	FITTING-RE,#4R5 TO #4FJIC	9.82	9.82
1	HE2170	HOSE-HYD/AIR #4X250' 100R	2.84	2.84
1	1010-1	CLAMP-EXHAUST VEE BAND	18.70	18.70
2	05-16401	MOUNT-ENGINE RUBBER	37.63	75.26
2	05-09121SPL	WASHER-SNUBBING RND 3/4X3	7.22	14.44
2	05-09057SPL	WASHER-SNUBBING RND 3/4X2	6.20	12.40
2	hwc06874	NUT-HEX SL NYL 3/4-16NFX0	2.12	4.24
2	HWC06894	NUT-HEX SL NYL 5/8-11NCX0	1.89	3.78
4	HWC01045	SPACER-ROUND 5/8X3X0.12T	1.63	6.52
1	D2920-8306	CLAMP-T BOLT XP 3 X 3-3/8	3.61	3.61
4	CT300LSS	CLAMP-CONSTANT TORQUE 2-1	8.66	34.64
2	P534925	FILTER-AIR	103.80	207.60
2	D1030-2728	HOSE-RADIATOR #48 J20R1-A	22.20	44.40
2	D1030-2650	HOSE-RADIATOR #40 1 PICK=	18.02	36.04
24	CT05512	TIE-CABLE 120LB, 15.25" B	0.52	12.48
1	RC0730	CAP-RADIATOR 7 PSI	7.67	7.67
1	L92-6000-0718	CABLE-HOOD	13.95	13.95
10	500004741	OIL-ROTELLA T TRI P 15W40	13.27	132.70
1	10R9350	KIT ENG OVER	10,732.40	10,732.40

CUSTOMER

Work Order

S84630

Invoice Date: 02-26-15

Year	Make / Model	VIN	License	Mileage	Unit / Stock	Key Tag
2000	PETERBILT / 379	1XP5DB9X7YN522434	A84454	1325945	03	

Open Date / Time	Delivery Date	Delivery Mileage	CPL/ARRG	Service Writer	Authorization	P.O. Number
02-11-15 / 09:38AM	01-01-00			CC*BS		

Engine Model / Serial #	Transmission Model/Serial #	Rear Axel Model/Serial #	Rear Ratio
/	/		

Complete	Memo
02-26-15	

1	10R9350#	CORE	7,038.35	7,038.35
1	0R7923	TURBO GP	2,441.65	2,441.65
1	0R7923#	CORE	995.85	995.85
6	2773076	TUBE AS.-OIL	83.83	502.98
1	6I4421	PLATE SPACER	421.76	421.76
2	4C4200	PAINT YEL	9.05	18.10
4	1083612	SPACER	14.87	59.48
1	1425867	SEALGP	77.86	77.86
1	10R3292	CAMSHAFT	1,014.78	1,014.78
1	10R3292#	CORE	643.84	643.84
2	20R3322	ARMA UI ROC	207.55	415.10
2	20R3322#	CORE	78.18	156.36
2	10R4704	ARM AS ROCKR	212.85	425.70
2	10R4704#	CORE	136.88	273.76
1	10R1364	ARM AS-V	145.35	145.35
1	10R1364#	CORE	74.49	74.49
1	20R3318	ROCKER ARM	126.37	126.37
1	20R3318#	CORE	47.59	47.59
1	1221486	HARNESS AS	226.88	226.88
1	7W6158	HOSE	42.37	42.37
1	1152420	BOLT AS	22.10	22.10
-1	0R7923*	CORE TBRB	995.85	-995.85
-1	10R3292*	CORE TBRB	643.84	-643.84
-2	20R3322*	CORE TBRB	78.18	-156.36
-2	10R4704*	CORE TBRB	136.88	-273.76
-1	10R1364*	CORE TBRB	74.49	-74.49
-1	20R3318*	CORE TBRB	47.59	-47.59
-1	10R9350*	CORE TBRB	7,038.35	-7,038.35
1	3163087	LUBRICANT	13.41	13.41
4	V07-03286RUB	RAD-MOUNT	23.10	92.40
1	CH1-4	4" CLAMP KIT	5.37	5.37
4	ET-B31ELHS	BUTT CONNECTOR 16-14 GAUGE	2.70	10.80

SHOP EXPENDABLES	15.00
TECHNICAL ADVISOR	50.00
HAZARDOUS WASTE	15.00

- - - -

Work Order

S84630

Invoice Date: 02-26-15

Year	Make / Model	VIN	License	Mileage	Unit / Stock	Key Tag
2000	PETERBILT / 379	1XP5DB9X7YN522434	A84454	1325945	03	

Open Date / Time	Delivery Date	Delivery Mileage	CPL/ARRG	Service Writer	Authorization	P.O. Number
02-11-15 / 09:38AM	01-01-00			CC*BS		

Engine Model / Serial #	Transmission Model/Serial #	Rear Axel Model/Serial #	Rear Ratio
/	/		

Complete	Memo
02-26-15	

whichever expires first after the completion of repair. THE FOREGOING WARRANTY IS EXCLUSIVE. THE COMPANY MAKES NO OTHER WARRANTIES WHETHER EXPRESSED OR IMPLIED INCLUDING WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE. The parts warranty shall be specifically limited to the supplier or manufacturer of the part, assembly, or component. The extent of THE COMPANY's liability under this warranty is expressly limited to repairs made to correct such defects as stated above. The buyer of lessee's sole and exclusive remedy under the warranty shall be the correction of the defect only, and THE COMPANY will, in no event, be liable for any failure resulting from negligence or breach but not limited to: down time, inconvenience, damage, or injury to the person or property, or any expenses resulting from a defect or defects in workmanship or materials (products). THE COMPANY neither assumes nor authorizes anyone else to assume for is, any other obligation or liability whatsoever. The warranty contained herein is void if the vehicle has been subject to misuse, negligence, accident or any operation contrary to the manufacturer's recommendation.

_____

Received By

CUSTOMER